Sanitized Copy Approved for Release 2011/05/10 : CIA-RDP78-03642A001200020051-0

SICA		
	Total file	
	July 1, 1958	
	2	5 X 1
In reference to our meeting Mond should be mailed to the following add	,	5 X 1
should be mailed to the Tollowing add		5X1
	Yours truly,	
		5X1
: dm		
		25
SECRET		

Sanitized Copy Approved for Release 2011/05/10 : CIA-RDP78-03642A001200020051-0

INTEROFFICE MEMORANDUM

June 30, 1958

To:	25	5 X 1
From: SUBJECT:	EP-3006.02 QUOTATION FOR FIVE (5) SETS OF DOORS FOR C-54 AIRCRAFT	

- kits each of which will provide for the installation of a set of double inward opening doors to replace the present cargo door in the aft portion of the C-54 aircraft. The doors will be manually operated and would be supported by a set of overhead rails and rollers which would carry the doors inward and upward so that they are positioned overhead when opened. In preparing this quote, we made a cursory examination of the C-54 and prepared the very preliminary layout attached hereto. This generally defines a way of accomplishing the job. The actual design will be determined during the initial part of the proposed program and after more detail information on the aircraft is obtained.
- Our estimated schedule for this work is as follows:

Engineering and preparation of drawings - 2 months

Delivery of first kit - 3 months after release of drawings

Delivery of 4 additional kits - 1 per month after completion of first kit

3. Our estimated cost for accomplishing this work is as follows:

Design a double inward opening door to replace the present cargo door on the C-54 aircraft and manufacture 5 kits to include the doors, operating mechanisms and supporting structure. These kits will permit ready installation in the field.

Total Estimated Cost \$59,849.37
Fixed Fee 4,180.00
CPFF \$64,029.37

obtain a copy of the stress reports covering the present door and the sur-

Page 2

IOM,					d	dated 6-30-58										25X1	
•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•		
	-		the C-	-54 be	ing	modif	ied.	In a	vork we ddition	, 1t	would	be	highl	y			

_____ 25X1

djm

rounding structure.

Attachments: 1. Layout of doors.

2. Cost Analysis EP-3006.02.

TITLE 6-34	CARGO	LOOK	HODIF	-ICHTION	<u></u>	Sheet _				
COST ANALYSIS	EP <u>300</u>	602				of _	/			
ITEM NO. DESCR.	INWARD	OPENING	Dock	15 (5 SET	()			T		
COST ELEMENT	HRS. & RATE	DOLLARS	HRS. & RA	TE DOLLARS	HRS.	& RATE	DOLLARS	HRS.	& RATE	DOLLARS
Engineering Labor	Hrs. 2087 Rate 3.58	7471,46	Hrs.		Hrs. Rate			Hrs. Rate	<u>u naje</u>	DOLLARS
Engineering Overhead	Rate 80%	5977.17		%	Rate	%		Rate	%	
Manufacturing Labor	Hrs. 7054 Rate 2,51	16,299.74	Hrs. Rate		Hrs. Rate	-		Hrs. Rate	-	
Manufacturing Overhead	Rate /05%	17,109.48	Rate 9	%	Rate	%		Rate	%	
Tool Labor	Hrs. 370 Rate 3,00	1,110.00.	Hrs. Rate		Hrs. Rate			Hrs. Rate		
Tool Overhead	Rate 105%	1,165.50	Rate 9	%	Rate	%		Rate	%	
Tool Material		250.00								
Subcontract										
Material & Purch. Parts		1 2,540.00								
Direct Charges		2,000.00								
	,				 			-		
Cost Excluding G&A		53 918,35								
G & A	// %	5931.02		76		%			%	
Total Estimated Cost		59,849.37								
FF	%	4.180.00		6		%			%	
CPFF		64.029.37								
Unit Price										
Extended Price or CREE										

Sanitized Copy Approved for Release 2011/05/10 : CIA-RDP78-03642A001200020051-0

25X1

Sanitized Copy Approved for Release 2011/05/10 : CIA-RDP78-03642A001200020051-0

Prepared b

Checked b

Approved b

Date

Submitted to _

Customer's Prop. Ref. __

AAInc. Prop. Letter